

DMA - TA Q800

Warning: This instrument may only be operated by those who have been trained by AAF staff and have read and signed the AAF laboratory policies.

- 1) DSC/DMA Computer: Computer should be left on (Password: dscaaf)
 - 1.1) **Program: TA Q Series Q800 / (Bottom icon Program Open in TA Instrument Explorer) Click (if icon/explorer program not open on bottom ask S Hardcastle)**
 - i) In middle panel – Three tabs (Summary, Procedure, Notes)
 - ii) **Start in Summary** – Sample information, fill in as needed
MODE DMA Multi-Frequency Stain (constant $\Delta l/l$); Multi-Frequency Stress (constant force); Creep; Stress Relaxation
Each mode has its own custom settings
 - b) Clamp/Sample needs to be loaded and calibrated correct clamp (see 1.2c)
 - c) Sample shape and dimensions need to be measured and entered (l,w,t).
 - d) Data file C:\TA\Data\DMA\your folder\your filename
 - e) *Example*
DMA Mode Creep : Test : Creep, custom Creep TTS (time_temp superposition)
Test: Creep - Constant Force (temperature) and measure creep for time t_a and measure recovery t_b . (in Procedure tab)
A pre-load force is needed (.01N or 0.1N ??)
 - Next Procedure**
 - f) Test Creep fill in preload (.01N??), Stress (xxMPa – need to know sample), Isothermal Temp (-120C to 600C), Soak Time, Recovery Time
Advanced: method start auto zero displacement (after isothermal)
Post: Return to temperature T (23C??) at end of run. Open furnace (no?)
 - iii) Notes tab Name
 - A Poisson Ratio if known.
 - B operator User
 - C Air bearing Air
 - 1.2) **Load Sample**
 - a) Open Furnace (Control Tab {top left} – Furnace open)
 - b) Check clamp replace with correct clamp (each clamp has calibration procedure)
3 point bend (20mm)
Single or dual cantilever (20 or 40mm, needs to be measured more accurately)
Tension (can be used with “floppy” samples or fibers)

- c) Calibrate clamp if needed (user must be trained) {On Bookmark Toolbar – clamp procedure you tube videos found}
- d) Place sample in clamp (must have correct dimensions)
Ideally thickness is one tenth width. Thickness < 1-2mm
Enter dimensions (cantilever length needs to be measured).
- e) Close furnace

1.3) Start Data Run

- a) Check Sample Information is correct
- b) In TA Q Series Program window left click Apply button {bottom center tab}
- c) Green Arrow (top left) is now active. {In left standard sequence table – only one run, see sequence number – red arrow, yellow dot – Run 1 (if dot is red check mark, double click check mark to “change” to yellow dot)}
- d) Left click Green (start) Arrow to start data run (“man” walking should be seen below arrow)
- e) A hissing sound will be heard throughout experiment (normal)

1.4) Obverse/Analyze Data

- a) The second farthest right ICON in TA Instruments is WinUA(Universal Analysis) Left Click (It may already be open, check open programs icons)
- b) Open Data File (same folder above...)
 - i) Data file information appears
 - ii) Signals
 - a) Y axis can display up to 4 signals (Creep use displacement can view force, stress)
 - b) X axis can display Time
 - ii) If Data is being collected, make sure Auto Refresh Data is checked in Graph Tab of UA program.

1.5) Save Sample File

1.6.1) Data is automatically saved ***.001 file

1.6.2) In UA File Save data as Text or Spreadsheet Type

- a) Highlight data file graph to be saved: Click File tab - Export – File Plot Signals – Choose ASII (Text) or Spreadsheet file - Finish – Edit file name and folder (If needed) - SAVE

1.6) Remove Sample end of experiment run

- 1) Allow Sample/Furnace to Remove “caps”
- 2) Open Furnace
- 3) Remove sample from clamp
- 4) Leave clamp in position

1.7) Clean up DMA area

1.8) Sign in usage in DMA Log book