

Cleaning instructions:

Aero S:

1. Clean cycle will start after the measurement
2. Vibration and feed rate will go to Max to make sure no particle is left in the cell
3. After the clean cycle close the measurement window and check the background

A good background is:

less than 100 on detector 1
less than 20 on detector 20
continuously decreasing curve

4. Repeat the cycle if more cleaning is required
5. If the background does not reach the above values the windows need to be cleaned
(Check with AAF staff)